


BASE LINE.



Description of the quality of the land on the interior sectional lines.

Total 26,063.16

Scale of Forty Chains to an Inch.

Surveyed by Aaron Dayton and Jos. Fowler 1855 and 57


Section	Quality	Section	Quality	Section	Quality
25 - 26	Hilly, good soil, bushy	27 - 28	Good soil, grapevines &	15 - 16	Good soil; timber Oak, Hickory &
27 - 28	Similar	29 - 30	Rich, open woods; timber Locust, Poplar &	17 - 18	Similar
29 - 30	Good soil, timber Oak, Sugar &c.	31 - 32	Level, rich, timber Oak &	19 - 20	Fine farming land; timber Oak, Poplar &
31 - 32	Similar	33 - 34	Bushy, Oak timber	21 - 22	Hilly, rich, timber Oak, Poplar &
35 - 36	Very good bushy	35 - 36	Similar	23 - 24	Thin soil, steep from points of knobs, timber Oak &
37 - 38	First rate farming land; timber Poplar, Oak &	37 - 38	Good soil, bushy, in the knobs	25 - 26	Rolling, good soil; timber Oak, Walnut &
39 - 40	Similar	39 - 40	Broken points of knobs	27 - 28	Similar
41 - 42	Similar	41 - 42	Good soil; timber Oak, Walnut &	29 - 30	Bushy thicket
43 - 44	First rate, timber Poplar, Walnut &	43 - 44	Similar	31 - 32	Good soil, Oak timber, bushy
45 - 46	Similar	45 - 46	Level, thin soil, part steep gullies and hills	33 - 34	Ridgy, bushy, Oak &
47 - 48	Similar, some bottom	47 - 48	Bushy, hilly; timber Oak &	35 - 36	Steep points and hills; timber Oak &
49 - 50	Rolling first rate, timber Oak, Walnut &	49 - 50	Steep bushy knobs	37 - 38	Similar
51 - 52	Similar, more than ridgy	51 - 52	Similar	39 - 40	Similar
53 - 54	Similar	53 - 54	Similar	41 - 42	Hilly, bushy, hilly &
55 - 56	Similar	55 - 56	Good soil; timber Oak, Walnut &	43 - 44	Good soil, ridgy, bushy
57 - 58	Very bushy, hilly &	57 - 58	Poor bushy knobs	45 - 46	Hilly, bushy
59 - 60	Good soil, Oak timber	59 - 60	Similar	47 - 48	Poor points of knobs; timber Oak &
61 - 62	Good soil, level & rolling, timber Oak, Hickory &	61 - 62	Similar	49 - 50	First quality
63 - 64	Rich, hilly; timber Oak &	63 - 64	Similar, part bottom	51 - 52	Rich soil; timber Oak, Maple &
65 - 66	Good soil, grapevines &	65 - 66	Good soil; timber killed by fire	53 - 54	

140



NATIONAL ARCHIVES OF THE UNITED STATES  
CARTOGRAPHIC RECORDS RG 49





Tron 1 South, Range 5 East. 2 PM

Plus Copy of 5737.44  
James M. Mansfield  
Supt. Gen.

